

City of Manitou Springs May 2015 Storm Event dr 4229

PDA #	FEMA Cat	Priority #	COMS JOB CODE	PW#	Project Name	Description	Original Estimated Cost	Repair Complete?	Funding Source	Actual Cost	Over/Under	Lat	Long	Historic?
1	A	21	1501	EP101	Williams Canyon PH 1 C and SB	sediment removal	\$13,026.27	yes, twice		14312.22	-\$1,285.95	38.862924	-104.917181	
2	C	5	1502		Manitou Terrace	slope and wall failure	\$308,480.81				\$308,480.81	38.863160	-104.917745	Yes
3	MULTI	9	1503		356 Ruxton Ave	sinkhole above xing, Needs SE	\$600,251.64				\$597,934.67	38.857829	-104.926320	In District
3A	A		1503	EP101	356 Ruxton Ave	sinkhole above xing, debris removal				1194.21		38.857829	-104.926320	In District
3B	B		1503	EP103	356 Ruxton Ave	sinkhole impacting public roadway				1122.76		38.857829	-104.926320	In District
3C	C		1503		356 Ruxton Ave	structural engineering for bridge damage						38.857829	-104.926320	In District
4	MULTI	n/a	1504		Pawnee Det Basin	bank and bed failure	\$122,650.00	no	NRCS EWP		\$105,966.59	38.851512	-104.916070	
4A	A		1504	EP101	Pawnee Det Basin	bank and bed failure/sediment removal				16683.41		38.851512	-104.916070	
4F	F		1504		Pawnee Det Basin	bank and bed failure/severe scour						38.851512	-104.916070	
5	C	35	1505	EP108	Water Treatment Access Rd.	washout, several locations	\$13,899.58				\$13,899.58	38.865921	-104.927595	
6	MULTI	60	1506		Mesa Tank Road	300' eroded away	\$7,799.34	yes			\$4,964.38	38.861755	-104.926138	
6A	A		1506	EP101	Mesa Tank Road	300' eroded away				2834.96		38.861755	-104.926138	
6C	C		1506	EP108	Mesa Tank Road	300' eroded away						38.861755	-104.926138	
7	A	22	1507		Pine Ridge Road	sediment removal	\$2,787.16	yes			\$2,787.16	38.860867	-104.923131	
8	C	23	1508	EP106	600 block of Ruxton	curb displaced, 30' section	\$20,000.00				\$20,000.00	38.853915	-104.934723	
9	C	39	1509	EP108	Pawnee Ave.	concrete pan damaged	\$9,228.47				\$9,228.47	38.853999	-104.914836	
10	C	20	1510	EP106	Fairmont Ave	v-ditch damaged	\$51,859.52				\$51,859.52	38.853349	-104.915514	
11	MULTI	4	1511		Spencer/Davon	wall failure	\$167,734.31				\$164,153.97	38.861746	-104.919901	Yes
11A	A		1511	EP101	Spencer/Davon	wall failure - debris/sediment removal				1290.17		38.861746	-104.919901	
11B	B		1511	EP103	Spencer/Davon	wall failure - temp stabilization				2290.17		38.861746	-104.919901	
11C	C		1511		Spencer/Davon	wall failure - need perm fix						38.861746	-104.919901	Yes
12	C	n/a	1512		Higgebotham EA Road	emergency access road	\$0.00	yes	fixed by Perco	0	\$0.00	38.862322	-104.919708	
13	MULTI	10	1513		Washington By-Pass	slope failure/sediment deposition	\$570,000.00	partial			\$569,263.95	38.859410	-104.912166	
13A	A		1513	EP101	Washington By-Pass	sediment dep				736.05		38.859611	-104.913067	In District
13C	C		1513		Washington By-Pass	slope failure/emergency egress and access						38.859410	-104.912166	
14	C	36	1514	EP108	El Monte Place	scour on pavement edge	\$1,797.22	yes			\$1,797.22	38.856550	-104.904433	
15	B	38	1515	EP103	Water Treatment Plant	filter issue from turbidity	\$5,496.60	yes			\$5,496.60	38.862942	-104.932445	
16	C	25	1516	EP106	Pinon Road	200' of eroded asphalt	\$3,372.25				\$3,372.25	38.858799	-104.908653	
17	C	19	1517	EP105	Oklahoma Road	gully in shoulder	\$113,104.00				\$113,104.00	38.854387	-104.910918	
18	C	37	1518	EP108	420 & 450 El Paso	Sink Holes	\$1,451.71				\$1,451.71	38.858986	-104.903477	
19	A	26	1519	EP101	Lover's Lane	slope failure and sediment dep	\$750.00	partial		192.8	\$557.20	38.858096	-104.913625	
20	A	40	1520	EP101	Plainview	sediment and debris on rdwy	\$1,212.91	yes	replaced culvert	631.21	\$581.70	38.854164	-104.909544	
21	A	43	1521	EP101	100 Block of El Paso	debris	\$1,995.96	yes		881.7	\$1,114.26	38.858736	-104.888634	
22	A	27	1522	EP101	Garden Drive	large debris	\$2,188.87	yes		750.11	\$1,438.76	38.859485	-104.897384	
23	MULTI	11	1523		Villa Vallecito	waterline subsidence from saturation	\$262,972.87	no			\$262,972.87	38.861110	-104.894920	
23B	B		1523	EP103	Villa Vallecito	waterline subsidence from saturation						38.861110	-104.894920	
23F	F		1523		Villa Vallecito	waterline subsidence from saturation						38.861110	-104.894920	
24	C	18	1524	EP106	Keithly Road	sinkhole and clogged culvert	\$214,777.34				\$214,777.34	38.853501	-104.899309	
25	A	42	1525	EP101	Old Crystal Park Road	debris on road	\$3,078.08				\$3,078.08	38.857042	-104.896180	
26	A	n/a	1526	EP101	Wildcat Gulch at Crystal Park Road	sediment deposition	\$2,903.35	yes		2840.06	\$63.29	38.843526	-104.902674	
27	MULTI	24	1527		Crystal Valley Cemetery	sediment deposition / culvert	\$99,577.58	partial			\$96,091.87	38.851636	-104.904416	Yes
27A	A		1527	EP101	Crystal Valley Cemetery	sediment deposition				3485.71		38.850797	-104.904933	Yes
27C	C		1527	EP101	Crystal Valley Cemetery	culvert and embankment failures						38.851636	-104.904416	Yes
28	A	6	1528	EP102	Fountain Creek	Sediment deposition	\$142,119.35				\$142,119.35	38.858146	-104.909326	
29	A	34	1529	EP101	Ruxton Ave, uppermost bridge	debris	\$1,394.11			1140.1	\$254.01	38.856162	-104.930224	
30	C	17	1530		Ruxton Ave., uppermost bridge	headwall damage, fissures	\$174,125.54				\$174,125.54	38.856174	-104.930225	Yes
31	C	33	1531	EP107	Reservoir access roads	sinkholes, gullying	\$60,000.00				\$60,000.00	38.884433	-104.993568	
32	F	16	1532		MS Recreation Center/Pool	waterline broken	\$25,000.00	yes			\$25,000.00	38.858042	-104.897958	
33	MULTI	28	1533	EP101	Burns Road	Rockfall, roadbed scoured	\$2,572.20	yes partial			\$1,108.10	38.859371	-104.911401	
33A	A		1533		Burns Road	Rockfall, roadbed scoured				1464.1		38.859371	-104.911401	
33C	C		1533		Burns Road	Rockfall, roadbed scoured						38.859371	-104.911401	
34	C	1	1534		Spring Street Bridge (Ruxton Creek)	Culvert Failure	\$560,251.54				\$560,251.54	38.857221	-104.927045	
35	C		1535	EP108	Manitou and Minnehaha	Sink Holes	\$3,500.00				\$3,500.00	38.862714	-104.922510	
36	G	29	1536		Public Trails	15 points of severe erosion	\$66,688.51				\$66,688.51			
37	C	13	1537		Winter Street Bridge (Ruxton Creek)	slope failure, headwalls	\$174,125.54				\$174,125.54	38.856732	-104.928634	Yes
38	C	14	1538		Iron Spring Bridge (Ruxton Creek)	wingwalls, sagged coffin block	\$174,125.54				\$174,125.54	38.856693	-104.928254	Yes
39	C	8	1539		Church Street Bridge (Ruxton Creek)	needs structural evaluation	\$1,600.00				\$1,600.00	38.859041	-104.923253	Yes
40	MULTI	15	1540		Beckers Lane	bank erosion	\$78,088.54				\$78,088.54	38.861747	-104.892764	
40B	B		1540	EP103	Beckers Lane	bank erosion - temp stabilization						38.861747	-104.892764	
40C	C		1540		Beckers Lane	bank erosion - drainage of open channel						38.861747	-104.892764	
41	C	32	1541	EP108	Banks Place	culvert failure	\$54,035.37	yes			\$54,035.37	38.852609	-104.902721	
42	C	12	1542		Brook Street Bridge	arch failure	\$540,261.54				\$540,261.54	38.858696	-104.923987	Yes
43	A		1543	EP101	Reservoir sediment removal	Sediment Removal	\$74,901.74	yes			\$74,901.74	38.874260	-105.000278	
44	C	8	1544		Capitol Hill Bridge (Ruxton Creek)	needs structural evaluation	\$1,601.00				\$1,601.00	38.858788	-104.922546	Yes
45	C	3	1545		Serpentine Road (Fountain Creek)	headwalls, footers, etc	\$508,698.29				\$508,698.29	38.867198	-104.924099	Yes
46	C	7	1546		513 Canon	7x7 RCBC	\$14,896,140.71				\$14,896,140.71	38.861459	-104.916828	
47	C	8	1547		Manitou and Park Bridge (Fountain Creek)	needs structural evaluation	\$1,600.00				\$1,600.00	38.860297	-104.920396	
48	C	8	1548		Soda Springs Park Footbridge (Fountain Creek)	needs structural evaluation	\$1,601.00				\$1,601.00	38.859355	-104.919372	In District
49	C	8	1549		Manitou Avenue Bridge	Severe scour/need SE	\$1,600.00				\$1,600.00	38.859358	-104.919603	Yes
50	C	8	1550		Cheyenne Spring Bridge	Severe scour/need SE	\$1,600.00				\$1,600.00	38.859195	-104.918382	Yes
51	C	8	1551		Canon and Lover's Lane Bridge (Fountain Creek)	headwalls, SE needed	\$1,600.00				\$1,600.00	38.858460	-104.916733	Yes
52	C	8	1552		Lafayette at Lovers Lane Bridge (Fountain Creek)	headwalls, SE needed	\$1,600.00				\$1,600.00	38.857901	-104.916101	In District
53	C	8	1553		Wichita Parking Bridge (Fountain Creek)	headwalls, SE needed	\$174,125.54				\$174,125.54	38.857247	-104.914871	In District
54	C	8	1554		El Paso Bridge (Fountain Creek)	wingwalls, headwalls	\$35,709.49				\$35,709.49	38.857809	-104.912282	Yes
55	C	8	1555		Old Man's Trail Bridge (Fountain Creek)	needs structural evaluation	\$1,600.00				\$1,600.00	38.857777	-104.910356	Yes
56	C	8	1556		Mayfair Bridge	needs structural evaluation	\$1,600.00				\$1,600.00	38.858006	-104.903246	Yes
57	C	2	1557		Beckers Lane Bridge	Visual damage, needs SE	\$123,834.49				\$123,834.49	38.858123	-104.891451	
58	MULTI	41	1558		Oak Place Bank Failure	slope failure/sewerline needs headwall	\$2,656.59				\$2,656.59	38.853529	-104.899555	
58B	B		1558	EP103	Oak Place Bank Failure	protective measure of exposed utilities						38.853529	-104.899555	
58F	F		1558		Oak Place Bank Failure	slope failure/sewerline needs headwall						38.853529	-104.899555	
59	F	30	1559		32 Manitou Ave	slope failure/exposed utilities	\$35,308.02				\$35,308.02	38.857753	-104.889259	
60	C	31	1560	EP106	17 Fountain Place	fissure, roadbed failure	\$26,588.79				\$26,588.79	38.857048	-104.909626	
61	F		1561		Colorado Springs Utilities	affluent overages	\$63,000.00							
62	B		1562	EP104	Spring Street Temporary Bridge	tentative complete 8-21	\$135,000.00				\$135,000.00	38.857221		